TOP SECRET



PHOTOGRAPHIC INTERPRETATION REPORT

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

## PROBABLE TV/MICROWAVE LINE BETWEEN ARMAVIR AND MAKHACHKALA USSR

25X1

TOP SECRET

\_ 25X1

OCTOBER 1970
COPY NO 117
5 PAGES
PIR-064/70

GROUP 1: EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION



## TOP SECRET RUFF

PROBABLE TV/MICROWAVE RELAY LINE BETWEEN ARMAVIR AND MAKHACHKALA, USSR

- 1. A photographic search for a TV/microwave radio-relay line extending from Armavir to Makhachkala, USSR, revealed the existence of towers at eight separate locations listed below (Figure 1). This report contains a description of each tower, a location map, a photograph of one of the towers, and mensuration of the height of each tower.
- 2. Microwave antenna dishes were observed only at the Stavropol TV/Microwave Facility which contained two towers, one of which had a probable R60/120 microwave antenna dish mounted on it. The self-supporting lattice steel tower with the probable R60/120 microwave antenna dish was similar to the TV tower at Nalchik (Figure 2). A second unmounted R60/120 microwave antenna dish was observed on the ground within the support area of the Stavropol facility.
- 3. Six of the other locations had microwave signatures (a control building and fenced area), but antennas could not be seen. The support features for the remaining location were not completed; therefore this location did not have all the microwave signatures.
- 4. The entire search area was covered on KH-4 photography of good interpretability, and the cities of Armavir, Stavropol, Nalchik, Ordzhonikidze, Groznyy, and Makhachkala were observed of good interpretability. All measurements are accurate to within the limitations indicated, with a 95% confidence level.

Stavropol TV/Microwave Facility
44-59-00N 041-54-30E, BE None,

25X1

This self-supporting lattice steel tower cast a shadow which indicated a probable R60/120 microwave antenna dish. The tower was within a secured area which also contained a control building and three small support buildings.

This guyed lattice steel tower was located immediately east of Tower No 1 and adjacent to a small support facility. An R60/120 microwave antenna dish was on the ground within the support area.

25**X**1

25X1

- 1 -

25X1


Sanitized Copy Approved for Release 2011/08/02: CIA-RDP78T05162A000100010025-3

	TOP SECRET RUFF
	nomyssk RadRel Sta SSE
44-34	-45N 041-58-30E
•	
	rowave elements cannot be determined on these secured, guyed
	ceel towers. This facility also contained a control'building apport buildings.
	20N 042-37-15E.
	rowave elements cannot be determined on this secured, self-
	glattice steel tower. This facility also contained a control and three support buildings.
C	
	gorsk RadRel A <u>TV BC Center</u> 3-10N 043-04-50E
11105	7 2011 0 1 3 0 1 3 0 2 3
	s facility consisted of a self-supporting lattice steel tower, a ilding, and three support buildings.
control bu	ilding, and three support buildings.
control bu Nalch	ilding, and three support buildings.  ik TV Facility (Figure 2)
control bu Nalch	ilding, and three support buildings.
control bu Nalch	ilding, and three support buildings.  ik TV Facility (Figure 2)
control bu  Nalch  43-27  Thi	silding, and three support buildings.  Sik TV Facility (Figure 2)  -50N 043-34-40E, BE None,  s secured facility consisted of a self-supporting lattice steel
control bu  Nalch  43-27  Thi	rilding, and three support buildings.  This TV Facility (Figure 2)  7-50N 043-34-40E, BE None,
Nalch 43-27 Thi tower, a c	s secured facility consisted of a self-supporting lattice steel ontrol building, and two small support buildings.
Nalch 43-27 Thi tower, a c	diding, and three support buildings.  dik TV Facility (Figure 2) 2-50N 043-34-40E, BE None,  as secured facility consisted of a self-supporting lattice steel control building, and two small support buildings.
Nalch 43-27 Thi tower, a c	s secured facility consisted of a self-supporting lattice steel ontrol building, and two small support buildings.
Nalch 43-27 Thi tower, a c Ordzh 43-01	s secured facility consisted of a self-supporting lattice steel ontrol building, and two small support buildings.

**-** 3 **-**

25X1





This unsecured facility contained a self-supporting lattice steel tower. The poor interpretability of the photography precludes further identification.

NPIC/IEG/SD/EB Project 250810

25X1

**-** 5 **-**

Sanitized Copy Approved for Release 2011/08/02 : CIA-RDP78T05162A000100010025-3

## **TOP SECRET**

## **TOP SECRET**